




Data

| | |
|------------|------------------------|
| AS index | AB2003 |
| Kategória | Uhlíky pre alternátory |
| Výrobca | AS-PL |
| Náhrada za | Hitachi |

Vlastnosti produktu

| | |
|-----------------|-------|
| Napätie [V] | 12 |
| Grubość. [mm] | 6.00 |
| Šírka [mm] | 7.00 |
| výška [mm] | 15.50 |



Referenčné číslo (6)

| Number | Výrobca |
|-------------|----------|
| 140744 | CARGO |
| L160-1331 | HITACHI |
| JAAX19 | IKA |
| 23142-04P01 | NISSAN |
| 1154-003RS | RS |
| ABR5545 | WOODAUTO |

Využitie

HITACHI

| Referenčné číslo | Výrobca |
|------------------|---------|
| LR140701 | HITACHI |
| LR145701 | HITACHI |
| LR145701B | HITACHI |
| LR145701C | HITACHI |
| LR145701E | HITACHI |
| LR145701F | HITACHI |
| LR150704 | HITACHI |
| LR160702B | HITACHI |
| LR160703B | HITACHI |
| LR160707 | HITACHI |
| LR160708 | HITACHI |
| LR160709 | HITACHI |
| LR160710 | HITACHI |



| | |
|-----------|---------|
| LR170701 | HITACHI |
| LR170701B | HITACHI |
| LR170701E | HITACHI |
| LR170702 | HITACHI |
| LR170702B | HITACHI |
| LT12502 | HITACHI |
| LT12505 | HITACHI |

mitsubishi

| Referenčné číslo | Výrobca |
|------------------|------------|
| AH2030B6 | mitsubishi |

NISSAN

| Referenčné číslo | Výrobca |
|------------------|---------|
| 2310004P01 | NISSAN |

SUBARU

| Referenčné číslo | Výrobca |
|------------------|---------|
| 23700KA000 | SUBARU |
| 23700KA020 | SUBARU |
| 23700KA030 | SUBARU |
| 429906001 | SUBARU |
| 429906100 | SUBARU |