




## Data

|            |                             |
|------------|-----------------------------|
| AS index   | ARC5030                     |
| Kategória  | Usmerňovače pre alternátory |
| Výrobca    | AS-PL                       |
| Náhrada za | Mitsubishi                  |

## Vlastnosti produktu

|                  |     |
|------------------|-----|
| B+               | 17  |
| B+thread         | M5  |
| Vonkajší priemer | 107 |
| Mounting dist.   | 85  |
| Diode Amp.       | 30  |
| Diodes           | 8   |



## Referenčné číslo (10)

| Number       | Výrobca       |
|--------------|---------------|
| 135249       | CARGO         |
| CQ1080368    | CQ            |
| B336-18-W60B | MAZDA         |
| A860T30170   | MITSUBISHI    |
| A860X47770   | MITSUBISHI    |
| RM-38        | MOBILETRON    |
| 1106-029RS   | RS            |
| REC-589      | UNIPPOINT     |
| IMR8572      | WAI / TRANSPO |
| RTF49862     | WOODAUTO      |

## Využitie

### HYUNDAI / KIA

| Referenčné číslo | Výrobca       |
|------------------|---------------|
| OK01118300D      | HYUNDAI / KIA |

**MANDO**

| Referenčné číslo | Výrobca |
|------------------|---------|
| AB170035         | MANDO   |

**MITSUBISHI**

| Referenčné číslo | Výrobca    |
|------------------|------------|
| A002T39391       | MITSUBISHI |
| A002T80391       | MITSUBISHI |
| A002T83491       | MITSUBISHI |
| A002TA1191       | MITSUBISHI |
| A002TA3991       | MITSUBISHI |
| A002TA5891       | MITSUBISHI |
| A003T01691       | MITSUBISHI |
| A003T23700AA060  | MITSUBISHI |
| A2T39391         | MITSUBISHI |
| A2T80391         | MITSUBISHI |
| A2T83491         | MITSUBISHI |
| A2TA1191         | MITSUBISHI |
| A2TA3991         | MITSUBISHI |
| A2TA5891         | MITSUBISHI |
| A3T01691         | MITSUBISHI |
| A3T23700AA060    | MITSUBISHI |

**SUBARU**

| Referenčné číslo | Výrobca |
|------------------|---------|
| 23700AA060       | SUBARU  |